

Sold through Båtagent Sverige

www.batagent.se

Dan Göransson

dan@batagent.se

Tel: +46 (0) 704166409

Bavaria 35 Match
DE-BAV B35C6E404



Engine

- Volvo Penta MD2020, 19hp, 710 hrs
- Fuel capacity 90 L (approx.) diesel.
- 3-bladed folding Maxprop propeller, bronze

Sail and rig

- Seldén mast and rod rig
- Seldén mastbut/step, hydraulic adjustment.
- Seldén rod-kick with special cloth cover
- Spinpole carbon fibre
- X-a forestay with racing profile
- Furlex E200, electric
- Dyneema running rigging
- Main sail cover
- Main sail:
 - North Kevlar, needs service
 - North Softnorlam, good
- Fore sail:
 - North Genoa 1,5 kevlar
 - North Genoa 3 kevlar
 - Quantum roll jib, laminate, UV-protection needs change
 - North Gennaker, 2 pcs
 - North Spinnaker

Hull and deck

- Keel exchanged to MK2, +300kg, draft 2 m.
- 2 wishes Holmatro 44
- 2 wishes Harken 32
- Genoa/Jib sheet track with 2x Harken wagons, adjustable from cockpit.
- Large steering wheel, extra
- Winsch handles Harken x 2, Holmetro x 2
- Harken block and cleats
- Harken + Spinlock lockin cleat
- Sprayhood
- Cockpit tent, steel bows, special design, blue outside, white inside.

Instrument

- Raymarine ST2 90 displays on mast, unconnected
- Garmin plotter GPS 4008, Autopilot
- Garmin combi display at chart table
- VHF Radio M-Tech SX DSC
- Radio/stereo, CD player. Loudspeakers in bulkhead with special cover in wood.

Elektronics/Electrical equipment

- Regulator for solar panel charging
- 220 V central
- 1 x 65 Amp engine battery, 2022
- 2 x 115 Amp service batteries, 2022
- Battery charger, electronic control
- Bilge pump, electric and manual
- Navigation lights, LED-bulbs 2022

Comfort

- Webasto heater
- Stove: 2 burners and oven.
- Fridge
- Special made bed mattresses.
- Table in salon, special made version.
- Shower in cock-pit
- Special back-rests for pushpit, needs new cover.
- Special wood on walls in salon.

Safety equipment

- Anchor Bruce 10 kg, stainless steel
- "Ankarolina" 50 m reel. (approx)
- Anchor chain, 8 m (approx.)
- Watch, barometer, hygrometer bulkhead mounted.
- Spare mast, Isomat rod-rig (original) according to separate agreement.

Known problems, other

- Sail boat drive gasket/bellow/sealing not exchanged
- Fire extinguisher expired date.
- Sprayhood: 8mm hole in one window
- Cockpit tent: one window 3cm crack, one 5 mm hole in cloth on top.

Reservation is made for the above information as it is stated by the yacht owner only.