

Scanner 38



Sales Terms:

The seller reserves the right to freely choose the buyer, regardless of which bids are received.

Sold through:

Båtagent Sverige

Website: www.batagent.se

Contact: Jonas Claesson

Email: Jonas@batagent.se

Phone: +46 701 478048

Engine

- Volvo Penta 29 hk
- Year: 1990
- Diesel
- Fuel tank: 55 L
- Saildrive
- 3-blade folding propeller
- Freshwater-cooled
- Professionally serviced annually by Brohäll Marin
- Diaphragm replaced -22 by Brohäll Marin
- Replaced saildrive seal, repacked impeller pump, replaced cooling water valve, repacked gear housing (2022)
- Replaced impeller (2024)
- Repaired leaking injector (2024)
- New heat exchanger and exhaust elbow -2

Sails and Rigging

- Mainsail 38 sqm, UK/Syversen, Carbon, x-drive (2018)
- Self-tacking jib 46 sqm, UK/Syversen, Carbon, x-drive (2018)
- Sail covers for main and jib, UK/Syversen (2018)
- Ronstan Series 6 track system (2018)
- Gennaker 85 sqm (2000)
- Through-mast
- Fractional rig, double swept spreaders
- Sprayhood (2014)
- Windex
- New larger winch Andersen 40 ST port side for halyards, etc.

Comfort

- Aft canopy (2005)
- Toilet(s): 1
- Freshwater tanks: 175 L + 90 L
- Refrigerator: Isotherm
- Septic tank: 60 L
- Deck discharge: Yes

- Cockpit table: Yes (Lagun)
- Stove/oven: Stainless steel (2005)
- Hot water: Isotherm 15 L (2010)
- Heater: Webasto Air Top 3500 (2007)
- Radio CD/DVD: Sony (2007)
- TV antenna (2007)
- Remote shut-off for gas (2007)
- Aft water meter (2007)
- LED light strips port + starboard, 2x2.5 m with dimmer (2007)
- Remote control for stereo in cockpit (2007)
- Cockpit speakers: Sony (2007)
- Clock and barometer in brass
- Oil lamp mounted on mast
- Speaker selector switch for inside/outside (2007)
- New spring mattress aft cabin (2013)
- Movable solar panel (2018)
- New skylights (2022)
- Bowsprit with cassette ladder (2024)

Interior, Electrical, and Instruments

- Shore power 220V system with ground fault breaker
- Autopilot Autohelm (not permanently installed)
- Battery charger: 20 Ah
- Depth sounder
- House batteries: 3x75 Ah
- Starter battery: 75 Ah
- Rewired battery area with thicker cabling and installed Blue Sea 8080 control panel with main switch and automatic breaker for house circuits and crossover switch for emergency start (2007)
- Plotter: Raymarine AXIOM 9-9"
- Compass: Silva
- Radio CD/DVD: Sony (2007)
- Wind instrument: Raymarine ST60 (2007)
- VHF: Raymarine Ray 54 (2007)
- Battery monitoring system (2007)
- Charging relay: Septor 75 (2007)
- FM splitter (VHF antenna to FM radio) (2007)
- VHF antenna: Comoros AV53i
- Solar panel: NAPS with regulator (2007)
- Inverter 150 W (pure sine wave) with outlet (2007)
- LED tricolor/anchor light: Lopligh (2007)
- Forward-looking sonar: Echopilot Silver (2007)
- Input for movable solar panel with regulator (2018)
- New plotter: Raymarine AXIOM 9-9" MFD with Navionics Nav+ 44XG chart, mounted on pedestal bracket (2018)
- New tricolor top light (2018)
- New bilge pump (2019)
- New tank gauge and instrument (2019)
- New batteries (2022)

Miscellaneous

- Water in saildrive oil, prop shaft update and seal work: Brohäll (2009)
- New elk leather on the steering wheel -26
- New galley water pump Parmax 4, 16 l/min (2009)
- New wheel and pedestal cover (2020)
- New throttle control: Brohäll Marin (2011)
- New galley water pumps (2012, 2013)
- New heater burner (2014)
- New fuel pump bracket for Webasto heater (2015)
- Fuel tank cleaned due to water (2016, Brohäll Marin)
- Shore power intake repair in anchor locker (2017)
- Septic and toilet seacocks replaced: Brohäll Marin (2023)
- New stripes (2024)
- Winter cover frame: NOA with arms
- Transparent tarpaulin (needs repair, used 3 seasons)
- Electric bilge pump in bathroom
- Shower hose/handle in bathroom
- Older Dacron sails (main and genoa) by Gransegel
- Interior lighting mostly converted to LED
- Seawater deck wash outlets fore and aft
- Wall panels to divide aft cabin
- Stem fitting
- Double LPG bottles (PC 5)
- Spinnaker pole (mast-mounted)
- Toilet check valve replaced (2025)
- Mast: Isomat
- New halyard bag at pushpit (2025)
- Halyard bag at pedestal
- Winch handle bag at pedestal
- 2 winch handles
- New gas hoses (2025, marked 2024)
- New marine-grade gas regulator (2025)
- New gas tank straps (2025)
- Sprayhood refurbished (2025)
- Mooring lines

Known Issues

- Woodwork around companionway needs surface treatment
- Flooring near mast needs surface treatment
- Fire extinguisher needs service or replacement
- Minor gelcoat damages
- Minor surface damage on forward keel (glassed)
- GPS display has cracked glass with impaired visibility (function replaced by plotter)
- Log is non-functional (function replaced by plotter)

Note: All information in this equipment list is provided by the boat's owner. Båtagent has not been able to verify all equipment in detail; the information is assumed to be correct but cannot be guaranteed by Båtagent.