

## **Equipment list**

**Boat model: ELAN 31**

**Model year: 2006**

Free right of review applies, which means that the seller has the right to choose who will acquire the boat regardless of the bids received.

Sold through Båtagent.

[www.batagent.se](http://www.batagent.se)

---

### **Specs**

Length 9.40m

Beam 3.20m

Draft 1.85m

### **Sail and rigging (racing/cruising setup)**

Furling jib North Sails 3Di Nordac 2019. Repair and overhaul 2006.

Main North Sails 3Di Nordac 2019

Gennaker North Sails A3 SuperLite 2019 + Selden roller for gennaker 2024

Spinnaker North Sails S2 SuperLite 2019 with accessories

Cover for furling jib North Sails 2021

Sailbag and lazy lines North Sails 2019 for mainsail

Selden mast and boom

Selden Rodkicker

Harken winches

Selden extendable gennaker bowsprit

Selden GX furler to gennaker 2024.

### **Navigation and instruments**

GPS plotter Axiom 9" 2024

Simrad IS12 log, temp, depth, wind

Vindex

Autopilot Raymarine ST2000 from 2019 + remote S100, 2022

### **Engine and electricity**

Volvo Penta D1-20 18HP with sail drive and folding prop

Portable solar cell 110 W with regulator, Victron

### **Comfort**

Isotherm fridge

Gas stove/oven

Webasto diesel heater

Hot/cold water in galley, bath and bathing platform.

Extra mattress in foredeck.

Clock in cockpit

New work lighting over galley and nav table

### **Exterior**

Sprayhood

Coach tent.

Lagoon table

Teak in good shape in cockpit and bathing platform

New peke 2024

Anchor 10kg Rocna (main) + a smaller one in the stern.

Tarpaulin with tarp and clamps.

**Other**

New (and old) emergency flares

Fire extinguisher in galley 2024

New LPG hoses 2024

Rescue line

Newly manufactured tiller, 9 layers laminated. Renovated 2006.

Diesel tank inspected, no dirt 2025

Overhaul and recondition of jib 2026

Overhaul and recondition of sprayhood 2026

Measurement certificate E 8938

**Known issues on the boat:**

Overheating protection for hot water heater broken, must be replaced.

Resistance in the rudder at outer position to port.

Deck drain of septic tank possibly not working.

---

The information on the equipment list has been provided by the boat's owner. Båtagent has not had the opportunity to examine the equipment in detail, the information is expected to be correct but cannot be guaranteed by Båtagent. [www.batagent.se](http://www.batagent.se)