

J122 -2007

FR-JBE-22007 A707



Freedom of contract applies, which means that the seller has the right to choose who will acquire the boat regardless of the bids received.

For sale through Boat Agent Sweden

[www.batagent.se](http://www.batagent.se)

Niklas Gustafsson

Mail: [Niklas.gustafsson@batagent.se](mailto:Niklas.gustafsson@batagent.se)

Tel: +46 70 720 42 20 (and WhatsApp)

---

This document is automatically translated, there may be errors.

## Engine

- Engine: 28 hp Volvo Penta D1-30B
- Propeller: Gori 2-blade folding
- Drive system: S-drive
- Bow thruster: Slepner retractable bow thruster with remote control (2022)
- Starter battery: Lead battery (2022)
- Battery bank: 460 Ah GEL batteries. 4x115 Ah. (2022)

## Mast/Rigging

- Mast: High modulus carbon fiber, Hall-spars. (Painted 2018) Solid carbon fiber in spreaders.
- Standing rigging: Rod (2017)
- Running rigging: All running rigging and trim lines (2022)
- Mast jack: Hydraulic Holmatro pump (can be permanently installed)
- Backstay: Sailtec hydraulic backstay pump
- Self-tacking jib: Seldén self-tacking rail (2023)
- Electric winch: 1x Seldén E40i Electric (2022)
- Clutches: Upgraded to 4x3 Spinlock (2022)

## Electrical and Instrumentation

- GPS/Plotter: Raymarine Axiom 9" at the helm. Charts of Northern Europe (2022)
- Wind sensor: Raymarine wireless sensor (2023)
- Displays: 2x Raymarine Axiom 7" at the cockpit (2023), 2x TackTick mast displays, 3x Raymarine i70 displays
- Autopilot, Raymarine Ev200
- Heater, diesel
- Boiler

## Safety Equipment

- EPIRB
- Life raft (requires repacking)

Various equipment required for Fastnet Race included, including

- Radar reflector
- MOB bracelet
- Anchor kedger

## Other

- Sea mattresses (Original)
- Extra gas bottle (2023)

- Deck light in mast with integrated lantern (LED) (2023)
- Engine room fan (2023)
- Stack pack (2022)
- Jib cover (2022)
- Hanging straps (2022)
- Fenders with fender covers (2022)
- Mooring lines (2022)
- New Jabsco toilet (2022)
- New LED lights in the forecabin with USB-C ports (2022)

#### **Known Issues**

- Pump for forepeak and toilet floor.
- Toilet tank / Not connected but everything is in place to connect to the toilet unit.
- Minor gelcoat damage to rail and transom.
- Crack in countertop/kitchenboard

The equipment list is provided by the boat owner. The boat agent has not had the opportunity to go through the equipment in detail; the information is expected to be accurate but cannot be guaranteed by the boat agent.