

Regina 43

Refit

Date	description
2017	spiral rigging
2018	North Sail 3D Nordac furling mainsail
2018	Genoa North Sail Dacron
2018	North Sail Nordac self-tacking jib
2016	Gennaker
20/06/2020	mast head VHF antenna change
21/06/2020	Horn replacement
22/06/2020	new bilge pump and new Hull drainage
22/06/2020	right stern winch overhaul watermaker overhaul, low pressure pump seal change, high pressure hose
08/07/2020	change, high pressure pump oil change, filter change
09/07/2020	placement of the generator
28/07/2020	Fixed cleats in the bow, changed the toilet in the bow
29/07/2020	removed solar panel and wind generator
01/09/2020	anchor chain + 25 m (total 90 m) arrangement of lifelines
10/09/2020	new bedroom fan aft
12/08/2020	flexible coupling change
20/08/2020	replacement of the propeller shaft bushing
15/09/2020	external table arrangement, new window for battery charger
18/09/2020	new 220 v electrical panel - new batteries
25/09/2020	plotter repair and new plotter
28/09/2020	new awning and spry wood
16/10/2020	right moorland infiltration repair
16/10/2020	propeller shaft removed, new case and shaft check, zinc change
16/10/2020	International 350 antifouling 3 coats 4 lt
18/10/2020	change of engine rubber hoses
20/10/2020	moved charger battery
10/01/2021	electrician for 220 panels, plotter re-aeration
10/02/2021	revision of the generator, replacing diodes, checking the electrical part
15/05/2021	alternator dismantling, watermaker washing line
20/05/2021	new bilge pump
21/05/2021	new "passerella"
03/06/2021	new autoclave and assembly
06/06/2021	new awning
05/06/2021	changed teleflex with mechanical lever
08/06/2021	new Rocna anchor 25 kg
10/06/2021	washing with acid exchanger
20/06/2021	change straps
02/07/2021	Propeller axis alignment and fixed blade propeller change redone
12/08/2021	silent block gearbox
30/08/2021	inverter disassembled and overhauled
30/08/2021	left winch aft overhauled
08/09/2021	new stern davit for tender engine
08/09/2021	new bathing ladder
30/09/2021	new fenders (x 4)
04/10/2021	replacement of the 1st right spreader pin and satin adjustment
15/10/2021	overhauled rollaranda engine
10/12/2021	inverter assembly, new flexible coupling (Victor9
10/02/2022	Seajet 034 antifouling 5.5 kg 3 coats
10/02/2022	changed all sea intakes with bronze guide intakes
23/05/2022	bow toilet pump replacement
16/06/2022	220 boiler and engine change
24/06/2022	watermaker washing and cartridge change, oil change
24/06/2022	forniture adjustments
06/09/2022	new left alternator
06/09/2022	engine service, oil filters, impeller, zincs
07/09/2022	new power fuse holders
20/07/2024	change three sea cocks, antifouling and hull polishing

TOTAL COST € 41.315,00