List of equipments

Boat Model : Sun Odyssey 40 DS

Year : 1998

WIN: IRI-054927F898

RIGGING_____

- Masthead rig
- Main sail with furling system
- Genoa with furling system (furler replaced in 2017)
- Main sail cover (2017)

ENGINE _____

- Volvo Penta Diesel MD22L 50HK
- Saildrive and fix propeller
- Fuel tank: approx 140L

MOORING –ANCHORING_____

- Anchor windlass
- Self draining anchor locker
- Bruce anchor

COCKPIT_____

- Sprayhood (new window 2024)
- Cockpit tent/Bimini
- Bathing platform with ladder
- Teak flooring in cockpit and on bathing platform
- One foldable cockpit table

SAFETY ON DECK_____

- 1 electric and 1 manual bilge pump
- Double guardrail and stainless steel stanchions

ELECTRONICS_____

- Plotter Garmin/GPS (2017)
- 2vOriginal Plotter Furuno (cockpit & inside)
- Autopilot (needs service)
- Windvane (do not function/needs service)
- Log and sounder
- VHF
- Radio/stereo CD with speakers inside and outside
- Erbespächer diesel heater (2017)
- Compass

GALLEY_____

- 2 burner LPG Gas stove with oven and LPG gas system
- Double stainless steel sinks
- Fridge
- Micro wave

SALOON TO STARBOARD_____

- Deck saloon with 360 view U-shaped seating area on starboard
- 2 armchair sofas with chart table on port side
- Led lamp

HEAD/SHOWER_____

- 2 heads with sink, toilet & shower
- Holding tank with sea and deck discharge

FORWARD CABIN_____

- Large double bed

- Combined lockers
- Shelves and beauty table along the hull

AFT CABINS PORT AND STARBOARD_____

2 Symetrical cabins each one consisting of:

- Double berths
- Storage lockers and shelves

ELECTRICITY _____

- 12 V circuit - 230 V circuit
- Shore power 230 V
- Batteries: 2x start 90Ah and 2 x service 130 Ah
- Solar panel 100W (2017)
- Voltmeter

WATER

_____

- Freshwater tank capacity - 320 L
- Pressurised electric water pump
- Electric water heater
- Shower drain pumps
- 1 Electric bilge pump - 1 Manual bilge pump

OTHERS_____

Emergency tiller

Fenders

The information on the equipment list is provided by the boat's owner. Båtagent has not had the opportunity to go through the equipment detail by detail, the information is expected to be correct but cannot be guaranteed by Båtagent.